


Maschhoffs New Minden Site Plan - 130220



Black arrows show the direction of storm water drainage. Barns are labeled as shown. A broken pipe in the west end of the north room of the north barn allowed whey feed to exit the barn, run across the limestone lot, and pool at the southwest end of the lot as shown by the red arrows. A temporary pit was dug at the edge of the limestone lot as indicated by a red oval where the whey and freshwater flush was collected. Collected whey and freshwater was placed in the under floor deep pits for land application. No feed or affected freshwater flush appeared to leave the site. An unnamed tributary drains north as shown by the blue arrows and appeared unaffected. No discharge was noted at the time of inspection.